



SIBERIA

PROFESSIONAL WIRING KIT 3X DT-CONNECTOR





12V DC Voltage Fuse 40A 60A Relay

Watt Max 3x 145W with DT

Max 420W if the DT is cutted

The kit includes: Wiring Kit, 2x blue duraseal, cable clamp, 3x DT-converter DT4 to DT2, manual.

Part No. 270478